


Tech Note 1020 - Recording Diagnostic Logging Scout 85.2 and above

• Description:

This feature is designed to enable the controller to capture logs 20 seconds prior to MMU flash activation. These logs can then be transferred to CUBIC Support for a diagnosis of the fault.

• Implementation:

To enable this feature, go to MM-8-8-5. Toggle "DiagnosticLog" to "ON."




Once "DiagnosticLog" is enabled, the controller will maintain a current 20 second log triggered to write to memory upon MMU flash activation (Alarm 15).

NOTE: These logs will be overwritten every time the MMU flash is activated!


Alarm/Event #15 must be enabled via MM-1-6-1 and 1-6-4

```
Event Enable
              Column.1.2.3.4.5.6.7.8
                                           Alarm Enable
                                                              Column.1.2.3.4.5.6.7.8
                                                  Alarm #s
Event #s
            9-16
                                                            9-16
           25-32
                                                           25-32
           33-40
                                                           33 - 40
           41 - 48
                                                           41 - 48
           49-56 +
                                                           49-56 +
```

With recorded log on controller, insert a USB and go to MM-8-8-8. Press enter and the logs will then be copied onto the USB.




Extract the file named "diag_log.dat" and send it to CUBIC Support for decoding.



• TS1/Caltrans Implementation:

To enable this feature when an MMU is not present you must redirect alarm #15 to Input Function #206-Cab Flash. (Other Input functions could be used, just an Input that goes active when monitor latches a fault.)

NOTE: Input can be seen in MM-1-9-7-1.



To do this go to MM-1-6-7-2 and set Alarm #15 to be equal to Input #206.

Idx 1		Fui = I	nction 206
2 3 4 5 6	Ö :	= I = I = I = I	0 0 0 0
7+			Ö

NOTE: This must be done for diagnostic logs to be capture on a TS1 or Caltrans cabinet.